

PM80 (Android 6) Release Notes



- [81.18 C1 \(Sep 18 2023\)](#)
- [81.18 \(Jul 21 2023\)](#)
- [81.17 \(Aug 10 2022\)](#)
- [81.16 \(Jul 12 2021\)](#)

81.18 C1 (Sep 18 2023)

- SDK: v3.21.0
- Security Patch: [2023-08-05](#)

Release Notes

PM80+ VoC

(FIXED)

Fixed the force close symptom of the Power Launcher when accessing the *Lock password* setting.
(Refer to [\[PM80+\] Power Launcher is force closed](#))

81.18 (Jul 21 2023)

- SDK: v3.21.0
- Security Patch: 2023-06-05

Release Notes

Operating System

(NEW)

Removed the default file explorer, ASTRO File Manager.
To use file explorer, install [Amaze File Manager](#) from Google Play.

- More> [\[PM80 Android6\] No file explorer app is installed](#)

81.17 (Aug 10 2022)

- SDK: v3.21.0
- Security Patch: 2022-06-05

Release Notes

PM80+ VoC

(NEW)	Added more mapping key behaviors in Program Buttons. <ul style="list-style-type: none"> CTRL + 4 / 5 / 9 SHIFT + Enter SHIFT + F2 More> Using Program Buttons
-------	---

SDK

(NEW)	Added APIs related to RFIDService.
-------	------------------------------------

EmKit

(NEW)	Scan2Set: Added sending intent feature with scanning the QR code <ul style="list-style-type: none"> More> Send Intent with Scanning QR Code by Scan2Set
(IMPROVED)	Power Launcher: Notifications are hidden when Power Launcher is running and setting as hiding Quick Settings.
(IMPROVED)	Scan2Set: Improved to start provisioning process starts once scanning the QR code in Setup Wizard without launching Scan2Set manually.

81.16 (Jul 12 2021)

- SDK: v3.19.7
- Security Patch: 2021-06-05

Release Notes

Find the VOC related to new version on the below table.

Location	VOC	Improvements
U.S.	Scan beam keeps on when pressing the scan button fast while entering the suspend mode.	Change to perform the scanner suspend process right after screen-off to prevent that scan beam keeps turned on while processing the other action.
Korea	Fail to boot up the device.	Fixed the booting error caused by an accidental change of user system directory.
	Searching Bluetooth is unavailable after disconnecting pairing.	Disconnect all Bluetooth pairing when turning off the Bluetooth to prevent the searching issue caused by the remaining connection.

Find the new functions/improvements on the new version of PM80 A6.

Added / Improved Functions
<ul style="list-style-type: none"> Google Security Patch (2021.01 - 2021.06)
<ul style="list-style-type: none"> [WLAN] Applied patch for FragAttacks to strengthen security vulnerabilities that affect Wi-Fi network.

- Display trigger enable status on notification icon of scanner.

- [Trigger Enable / Disable Indication](#)

- Check OS version on Setup Wizard screen.
 - Press power button until power menu pops up, then press Power off for 3 seconds.

- Added 5 blinks of LED when power is turned on with low battery

- **[RFID]** Added RFIDService API

- **[RFID]** Modified default TxCycle setting to Max (100%)